

UNDERWATER BRIDGE INSPECTION REPORT

STRUCTURE NO. 7003

CSAH NO. 38

OVER THE

BIG FORK RIVER

DISTRICT 1 - ITASCA COUNTY



PREPARED FOR THE
MINNESOTA DEPARTMENT OF TRANSPORTATION
BY
COLLINS ENGINEERS, INC.
JOB NO. 3512

MINNESOTA DEPARTMENT OF TRANSPORTATION
UNDERWATER BRIDGE INSPECTION

REPORT SUMMARY:

The substructure units inspected at Bridge No. 7003, Piers 1 through 5, were found to be in good to satisfactory condition with no significant deterioration. The timber piles were typically firm and sound with random minor checking, with more extensive checking and splitting present at two piles. There was a light to moderate accumulation of timber debris observed throughout the bridge and around all piers, especially across the upstream fascia.

INSPECTION FINDINGS:


- (A) Overall, the timber piles were firm and sound with random checking typically 1/8 inch wide and 1 to 3 feet long. Two piles exhibited more extensive checking and a 1/4-inch-wide by 3-inch-deep split extending from the top of the pile to the mudline.
- (B) Random 6- to 18-inch-diameter pieces of timber debris were scattered in and around all of the piers, and a light to moderate accumulation of timber debris was observed along the upstream fascia of the bridge.
- (C) A 3-foot-radius by 2-foot-deep scour depression was observed at the upstream pile of Pier 2.

RECOMMENDATIONS:

- (A) At this point, timber drift accumulation at the bridge is not excessive; however, it should be monitored, and if found to be progressing to an extent where excessive lateral loads may be exerted on the bridge or scour may be influenced, the drift may need to be removed at that time.
- (B) Reinspect the submerged substructure units at the normal maximum recommended (NBIS) interval of five (5) years.

I hereby certify that this plan, specification, or report was prepared by me or under my direct supervision and that I am a duly Licensed Professional Engineer under the laws of the State of Minnesota.

Daniel G. Stromberg



Date 6/30/2004 Registration No. 21491

Respectfully submitted,

COLLINS ENGINEERS, INC.



Daniel G. Stromberg
Registered Professional
Engineer, State of Minnesota

MINNESOTA DEPARTMENT OF TRANSPORTATION
UNDERWATER BRIDGE INSPECTION

1. BRIDGE DATA

Bridge Number: 7003

Feature Crossed: The Big Fork River

Feature Carried: CSAH NO. 38

Location: District 1 - Itasca County

Bridge Description: The bridge superstructure consists of six spans of timber deck on multiple timber stringers. The superstructure is supported by five timber pile piers and two timber pile abutments. The piers are numbered 1 through 5 starting from the west end of the bridge.

2. INSPECTION DATA

Professional Engineer Diver: Daniel G. Stromberg
State of Minnesota, P.E., No. 21491

Dive Team: Michelle D. Koerbel, Matthew J. Lengyel

Date: August 23, 2002

Weather Conditions: Sunny, $\pm 70^{\circ}$ F

Underwater Visibility: " 5 Foot

Waterway Velocity: " 0.5 f.p.s.

3. SUBSTRUCTURE INSPECTION DATA

Substructure Inspected: Piers 1 through 5.

General Shape: The piers each consist of six timber piles interconnected with timber cross bracing.

Maximum Water Depth at Substructure Inspected: Approximately 7.5 foot.

4. WATERLINE DATUM

Water Level Reference: The top of pile cap at north end of Pier 5.

Water Surface: The waterline was approximately 5.8 feet below reference.
Assumed Waterline Elevation = 94.2.

5. NBIS CODING INFORMATION (Minnesota specific codes are used for 92B and 113)

Item 60: Substructure: Code 6


Item 61: Channel and Channel Protection: Code 7

Item 92B: Underwater Inspection: Code B/08/02

Item 113: Scour Critical Bridges: Code U/02

Bridge is scour critical because abutment or pier foundation is rated as unstable due to observed scour at bridge site.

_____ Yes X No



SOUNDING PLAN

GENERAL NOTES:

1. Piers 1 through 5 were inspected underwater.
2. At the time of inspection on August 23, 2002, the waterline was located approximately 5.8 feet below the top of the cap at the north end of Pier 5. Since insufficient bridge elevation information was available a reference elevation of 100.0 was assumed. Based on the assumed reference the waterline elevation was 94.2.
3. Soundings indicate the water depth at the time of inspection and are measured in feet.
4. Soundings were taken parallel to the bridge at mid point intervals between the substructure units.

INSPECTION NOTES:


- 1 Overall, the timber piles were firm and sound with random checking typically 1/8-inch-wide and 1- to 3-foot-long.
- 2 Pile exhibited a 1/4-inch-wide, 3-inch-deep split extending from the top of the pile to the mudline.
- 3 A 3-foot-radius, 2-foot-deep scour pocket was observed at the upstream pile at Pier 2.
- 4 Random 6- to 18-inch-diameter pieces of timber debris were scattered on the channel bottom throughout the pier.
- 5 A moderate accumulation of timber debris was observed along the upstream fascia extending from 1 foot above the waterline to 1 foot below the waterline at Piers 3 and 4 and the span in between and from the channel bottom to the waterline at Pier 5.
- 6 The channel bottom consisted of silt with probe rod penetrations ranging from 1 to 2 feet along Pier 2 to 2 to 3 feet along Pier 1.
- 7 The channel bottom consisted of silty sand with a probe rod penetration of 6 inches.
- 8 The channel bottom consisted of sandy gravel with 3 inches of probe rod penetration.
- 9 The channel bottom consisted of sand and gravel with 1-foot-diameter cobbles with no probe rod penetration.

Legend


- 5.2 Sounding Depth from Waterline
- Timber Pile
- Battered Timber Pile
- Timber Debris
- Riprap
- Scour Depression

MINNESOTA DEPARTMENT OF TRANSPORTATION UNDERWATER BRIDGE INSPECTION		
STRUCTURE NO. 7003 OVER THE BIG FORK RIVER DISTRICT I, ITASCA COUNTY		
INSPECTION AND SOUNDING PLAN		
Drawn By: PRH Checked By: MDK Code: 35127003	COLLINS ENGINEERS, INC. 300 W. WASHINGTON, STE. 600 CHICAGO, ILLINOIS 60606 (312) 704-9300	Date: AUG. 2002 Scale: NTS Figure No.: 1

TYPICAL END VIEW OF PIERS




UPSTREAM FASCIA PROFILE



DOWNSTREAM FASCIA PROFILE

Note:
Refer to Figure 1 for General Notes.

MINNESOTA DEPARTMENT OF TRANSPORTATION UNDERWATER BRIDGE INSPECTION		
STRUCTURE NO. 7003 OVER THE MISSISSIPPI RIVER DISTRICT I, ITASCA COUNTY		
UPSTREAM AND DOWNSTREAM FASCIA PROFILES		
Drawn By: PRH	COLLINS ENGINEERS, INC.  300 W. WASHINGTON, STE. 600 CHICAGO, ILLINOIS 60606 (312) 704-9300	Date: AUG. 2002
Checked By: MDK		Scale: 1"=10'
Code: 35127003		Figure No.: 2



Photograph 1. Overall View of the Structure, Looking Southwest.



Photograph 2. View of the Timber Debris along Upstream Fascia, Looking West.



Photograph 3. View of Pier 5, Looking West. Typical Condition and Configuration of all Piers.

Reinspect the submerged substructure units at the normal maximum recommended interval of five (5) years.

MINNESOTA DEPARTMENT OF TRANSPORTATION
OFFICE OF BRIDGES AND STRUCTURES

UNDERWATER INSPECTION CONDITION RATING FORM

BRIDGE NO. 7003
INSPECTORS Collins Engineers, Inc.
ON-SITE TEAM LEADER Daniel G. Stromberg, P.E. 21491
WATERWAY CROSSED The Big Fork River

INSPECTION DATE August 23, 2002
NOTE: USE ALL APPLICABLE CONDITION
DEFINITIONS AS DEFINED IN THE MINNESOTA
RECORDING AND CODING GUIDE INCLUDING
GENERAL, SUBSTRUCTURE, CHANNEL AND
PROTECTION, AND CULVERTS AND WALL
DEFINITIONS TO COMPLETE THIS FORM.

CONDITION RATING

UNIT REFERENCE NO.	UNIT DESCRIPTION	MAXIMUM DEPTH OF WATER	SUBSTRUCTURE						CHANNEL					GENERAL					
			PILING	COLUMNS, SHAFTS, OR FACES*	FOOTINGS	DISPLACEMENT	OTHER (BRACING)	OVERALL SUBSTRUCTURE CONDITION CODE*	SCOUR	EMBANKMENT EROSION	EMBANKMENT PROTECTION	OTHER (DRIFT/DEBRIS)	OVERALL CHANNEL & PROTECTION CONDITION	CONCRETE	STEEL	TIMBER	LOSS OF SECTION	PREVIOUS REPAIR OR MAINTENANCE	OTHER
		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
	Pier 1	1.5'	7	N	N	9	7	7	8	N	N	7	7	N	N	7	7	N	N
	Pier 2	3.5'	7	N	N	9	7	7	7	N	N	7	7	N	N	7	7	N	N
	Pier 3	7.0'	7	N	N	9	7	7	8	N	N	7	7	N	N	7	7	N	N
	Pier 4	7.5'	6	N	N	9	7	6	8	N	N	7	7	N	N	6	7	N	N
	Pier 5	6.0'	6	N	N	9	7	6	8	N	N	6	6	N	N	6	7	N	N

*UNDERWATER PORTION ONLY

REMARKS: Overall, the submerged timber of Piers 1 through 5 was in good to satisfactory condition with no significant deterioration. The timber piles were typically firm and sound with random minor checking (up to 1/8 inch wide) throughout. At two piles more extensive checking and splitting (up to 1/4 inch wide) was present over the full height. The timber bracing was all firm and sound and adequately connected. There was light to moderate drift throughout the bridge and around all piers, especially across the upstream fascia.

NOTES: ATTACH SKETCHES AS NEEDED, IDENTIFY REMARK BY REFERRING TO UNIT REFERENCE NO. AND REMARK NO.
USE GENERAL SECTION TO IDENTIFY OVERALL PRESENCE OF SPALLS, CRACKS, CORROSION, ETC.